




Размеры воздуховок МТ 11-Т2С



Тип	Phases	A	B	C'	D	E	F	G	H	J	K	L	M	N	O	φP
МТ 11-Т2С-11,0	3~	500	550	336	356	394	694	318	300	197	170	217	312	212	165	G2 _{1/2}

Тип	φR	S	V	W	φX	YxZ	X-Holes
МТ 11-Т2С-11,0	15	66	4xM40x1,5	54	286	M12x20	0°/120°/240°