


Размеры воздуховок МТ 15-2СН-0,55



Тип	Phases															
ТИП	Фазы	A	B	B ₁	C	D	E	F	G	H	J	K	M	N	O	P
МТ 15-2СН-0,55	3~	294	319	39	87	260	298	293	129	167	111	105	252	65	124	G11/4(18 deep)

Тип														
ТИП	Q	φR	S ₁	S ₂	S ₃	T	T ₁	U	V	V ₁	W	φX	YxZ	
МТ 15-2СН-0,55	64	14	4	140	31	105	107	M6x17	M25x1.5	M16x1.5	32	153	M6x15	